

Preventive Maintenance

~ Recommendation for replacement of touch panel ~



- The Touch panel may have problems due to
 - ①_ **Degradation** of the Pressure-sensitive sensor.
 - ②_ **Failure** of the inverter base board for back light.
Blowout of the back light (**Expired life**)
 - ①'_ Degradation of the Pressure-sensitive sensor depends on the **frequency of use**.
 - ②'_ The inverter base board deteriorates in **power supply**.
We recommend **periodic maintenance**.

- The service life of back light is about **50,000 hours**
Under conditions of working time "24hours(day) x 25days(month) x 12months(year)"
= **7,200hrs/years**. The back light will blow out around **7 years**.

- If the touch panel is broken.
Delivery time will be **1 month**.

Please feel free to contact us at [Inquiry] or e-mail
for the maintenance/replacement of touch panel

Inquiries on matters other than the above
such as the **Quotation for parts, Modification and Maintenance of the Machine**
are also welcome.
Please feel free to contact us.

HAGIHARA
HAGIHARA INDUSTRIES INC.

荻原工業株式会社
Engineering business hdqrs.